WASHING



Washing







Machine wash

permanent press

Machine wash gentle or delicate

Do not wash





Wash at or below 30 °C

30

40 Wash at or below 40 °C


50 Wash at or below 50 °C

Wash at or below 60 °C

BLEACHING



bleach





Non-chlorine bleach when needed



Do not bleach



Do not bleach

Drying symbol





NATURAL DRYING





Dry flat



Dry in the shade

CHEMICAL CLEANING



Dry clean, tetrachloroethylene (PCE) only



Gentle cleaning

with PCE







Professional cleaning Dry clean, hydrocarbon solvent only (HCS)

Gentle cleaning with hydrocarbon

Very gentle cleaning with hydrocarbon solvents







Very gentle


cleaning with PCE



Do not dry clean

TUMBLE DRYING





(low temperature)

Gentle wet cleaning



(normal)



Do not tumble dry

WET CLEANING



Professional wet

cleaning





Very gentle

wet cleaning



Do not wet clean

IRONING





Iron at low

temperature



Iron at medium

temperature





Iron at high temperature



Don not steam