

WASHING



Washing

Machine wash permanent press

Machine wash gentle or delicate

Do not wash



Wash at or below 30 °C

Wash at or below 40 °C

Wash at or below 50 °C

Wash at or below 60 °C

Hand wash

CHEMICAL CLEANING



Professional cleaning

Dry clean, hydrocarbon solvent only (HCS)

Gentle cleaning with hydrocarbon solvents

Very gentle cleaning with hydrocarbon solvents



Dry clean, tetrachloroethylene (PCE) only

Gentle cleaning with PCE

Very gentle cleaning with PCE

Do not dry clean

BLEACHING



Bleaching allowed for both chlorine and non-chlorine bleach


Bleaching with chlorine allowed (obsolete)

Non-chlorine bleach when needed

Do not bleach

Do not bleach

TUMBLE DRYING




Tumble drying symbol

Tumble drying (low temperature)

Tumble drying (normal)

Do not tumble dry

WET CLEANING



Professional wet cleaning

Gentle wet cleaning

Very gentle wet cleaning

Do not wet clean

NATURAL DRYING



Drying symbol

Line dry

Do not line dry




Dry in the shade

Line dry in the shade

Do not line dry in the shade

IRONING



Ironing

Iron at low temperature

Do not iron



Do not iron

Do not iron

RYING



Dry flat



Drip dry



Dry in the shade



Drip dry in the shade

G



Iron at medium temperature



Iron at high temperature



Do not steam